



Photo 3 : Visibilty at egress from site (southside)
Setback = 1.3m



Photo 4 : Visibilty at egress from site (northside)
Setback = 1.3m